

# BRIGHT BEADS, ART

## INSTALLATION GUIDE




**FRAGILE FINISHES** PLEASE WEAR GLOVES DURING INSTALL

**DANGER:** LIGHTS MUST BE INSTALLED BY A QUALIFIED ELECTRICIAN. ELECTRIC SHOCK RISK. TURN OFF ELECTRICAL POWER BEFORE BEGINNING INSTALLATION AND USE CAUTION WHEN INSTALLING.


- PLEASE DO NOT MODIFY OR ADJUST ANY FIXTURE IN A WAY THAT IS NOT CLEARLY STATED OR INTENDED.
- ALWAYS ENSURE THE POWER IS OFF AND THE LUMINAIRE HAS COOLED DOWN BEFORE PERFORMING ANY MAINTENANCE, CLEANING OR ADJUSTMENT TO THE FITTING.
- TO AVOID INJURY OR DAMAGE TO THE LUMINAIRE, ENSURE THAT POWER LEADS AND SCREWS ARE SECURE BEFORE CONNECTING THE POWER.
- SELECT A SUITABLE LOCATION AWAY FROM LIQUIDS AND HAZARDS.
- TO CLEAN, WIPE WITH A SOFT DAMP CLOTH. DO NOT SOAK OR IMMERSE THE LUMINAIRE IN WATER OR OTHER LIQUIDS.
- ENSURE THAT THE LUMINAIRE DOES NOT COME IN CONTACT WITH CORROSIVE CHEMICALS/SOLVENTS OR ABRASIVE CLEANERS ETC.

# BRIGHT BEADS, ART


## INSTALLATION OPTIONS



Face Mount  
(Standard)




Flush Trimless  
(Bracket not  
supplied)



Flush Recessed  
(Bracket not  
supplied)

## INSTALLATION GUIDE, FACE MOUNT



## INSTRUCTIONS

**1.** Remove magnetically attached Cosmetic Plate (D), taking care not to damage surrounding lip, then undo three screws (C) and remove Tool Plate (B).





**2.** Fix Canopy Shell (A) to ceiling through 5mm slots (fasteners not included).

**3.** Connect mains power supply and earthed connection to the terminal block.

Continued next page.

# BRIGHT BEADS, ART

## INSTALLATION GUIDE



### INSTRUCTIONS

**4.** Slide Cosmetic Plate (D) first and then slide Tool Plate (B) second onto Flex (E). Install Cord Grip (F) onto Flex (E).

**5.** Connect Flex (E) into Canopy (A) terminal block.

**6.** Reinstall Tool Plate (B) using Screws (C) supplied.

**7.** Snap Cosmetic Plate (D) into place.

